

Work Order ID 165114

Tuesday, August 15, 2017 3:20:33 PM

165114

Page 1

Item ID: D4635-041 Accept ***N900040100*** Setup Start ***NS1***
Revision ID: Stop ***NS2***
Item Name: Fwd Ceiling Panel Assembly, LH
Start Date: 8/21/2017 Start Qty: 1.00 ***1*** Cust Item ID:
Required Date: 9/1/2017 Req'd Qty: 1.00 ***1*** Customer:
Reference:

Approvals: Process Plan: **DAS 21 9-89** Date: AUG 16 2017 Tooling: _____ Date: _____ Run Start ***NR1***
QC: _____ Date: _____ SPC (Y/N): _____ Date: _____ Stop ***NR2***

Sequence ID/ Work Center ID	Operation Description	Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
Draw Nbr	Revision Nbr								
D4635	F								

100

0.00

100

HandThermo

Memo

0.00

Hand Finishing Thermoforming

Pick Kit

SEP 13 2017**DAS**
6
9-89

110

0.00

110

Small Fab

Memo

0.92

Small Fab

1- Assemble as per Dwg D4635-041

2-Install speakers

3- Install Air valves

4-Install Wiring Harness

5-Install wiring harness

DAS
07
9-8917/09/15

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____		DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐		AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐																																																													
Date :		Step #:		QTY Effective :				MRB (QSI042) Approval																																																									
Description Work Order Deviation				Disposition				Completed By Lead hand / Supervisor Approval Verification QC / QA Coordinator Approval																																																									
Root Cause		FAULT CATEGORY																																																															
Environment ☐	No Re-verification ☐	Pressure/Forced ☐	Temperature/Cure ☐	Power Loss/Surge ☐	Positioned Wrong ☐	Design ☐	Operator ☐	Bending ☐	Set-up ☐	Folio/Program ☐	Outside Dimensions ☐	Doc/Data ☐	Offset/Setup ☐	Centre Not Concentric ☐	BOM/Route ☐	Grain ☐	Over/Under tolerance ☐	Equip/Tooling ☐	Supplier ☐	Cracks ☐	Broken/Damage/Defect ☐	Weld ☐	Part Incorrect ☐	Handling/Pre ☐	Training ☐	Crimp/Kink/Ripple/Wave ☐	Inspection Incomplete/Unqualified ☐	Wrong Stock Pulled ☐	Part Lost/Missing ☐	Material ☐	Use for Testing ☐	Cuffs ☐	Contamination ☐	Out of Sequence ☐	Part Moved ☐	Internal Transport ☐	Poor Information ☐	Crushing ☐	Countersink ☐	Off-set ☐	Drawing ☐	Tribal Knowledge ☐	Rushing ☐	Heat Treat ☐	Cut Too Short ☐	Mislabeled ☐	Finish ☐	LOA ☐	Product Improvement ☐	Wave/Twist in Tube ☐	Instructions Incomplete/Unclear ☐	Fit/Function ☐	Misread ☐	Substation ☐	Process Improvement ☐	Marks/Chatter ☐	Drill Holes ☐	Misaligned/off center ☐	Turning Sequence ☐	Past Expiry Date ☐	Manufacturing Process ☐	OTHER :			
Misidentified ☐	Past Due ☐																																																																

Work Order ID 165114

Tuesday, August 15, 2017 3:20:33 PM

165114

Page 2

Item ID: D4635-041 Accept ***N900040100*** Setup Start ***NS1***
Revision ID: Stop ***NS2***
Item Name: Fwd Ceiling Panel Assembly, LH
Start Date: 8/21/2017 Start Qty: 1.00 ***1*** Cust Item ID:
Required Date: 9/1/2017 Req'd Qty: 1.00 ***1*** Customer:
Reference:

Approvals: Process Plan: _____ Date: _____ Tooling: _____ Date: _____ Run Start ***NR1***
QC: _____ Date: _____ SPC (Y/N): _____ Date: _____ Stop ***NR2***

Sequence ID/ Work Center ID	Operation Description	Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
--------------------------------	--------------------------	----------------------	---------	--------	--------------	---------------	---------------	------------------	----------------

120	QC5- Inspect part completeness to step on W/O	0.00							
-----	---	------	--	--	--	--	--	--	--

120

QC

Memo

Quality Control

0.02

130

Identify as per dwg & Stock Location: _____

0.00

130

Packaging

Memo

Packaging

0.01

140

QC21- Final Inspection - Work Order Release

0.00

140

QC

Memo

Quality Control

0.10

DAS
19
9-89DAS
15
9-89DAS
27
9-89

SEP 22 2017

17/9/25

WY 17/9/22

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____		DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐		AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐					
Date :		Step #:		QTY Effective :			MRB (QSI042) Approval		
Description Work Order Deviation				Disposition				Completed By Lead hand / Supervisor Approval Verification QC / QA Coordinator Approval	
Root Cause		FAULT CATEGORY							
Environment ☐	No Re-verification ☐	Pressure/Forced ☐	Temperature/Cure ☐	Power Loss/Surge ☐	Positioned Wrong ☐				
Design ☐	Operator ☐	Bending ☐	Set-up ☐	Folio/Program ☐	Outside Dimensions ☐				
Doc/Data ☐	Offset/Setup ☐	Centre Not Concentric ☐	BOM/Route ☐	Grain ☐	Over/Under tolerance ☐				
Equip/Tooling ☐	Supplier ☐	Cracks ☐	Broken/Damage/Defect ☐	Weld ☐	Part Incorrect ☐				
Handling/Pre ☐	Training ☐	Crimp/Kink/Ripple/Wave ☐	Inspection Incomplete/Unqualified ☐	Wrong Stock Pulled ☐	Part Lost/Missing ☐				
Material ☐	Use for Testing ☐	Cuffs ☐	Contamination ☐	Out of Sequence ☐	Part Moved ☐				
Internal Transport ☐	Poor Information ☐	Crushing ☐	Countersink ☐	Off-set ☐	Drawing ☐				
Tribal Knowledge ☐	Rushing ☐	Heat Treat ☐	Cut Too Short ☐	Mislabeled ☐	Finish ☐				
LOA ☐	Product Improvement ☐	Wave/Twist in Tube ☐	Instructions Incomplete/Unclear ☐	Fit/Function ☐	Misread ☐				
Substation ☐	Process Improvement ☐	Marks/Chatter ☐	Drill Holes ☐	Misaligned/off center ☐	Turning Sequence ☐				
Past Expiry Date ☐	Manufacturing Process ☐								
Misidentified ☐	Past Due ☐	OTHER :							

Picklist Print

Tuesday, August 15, 2017 3:20:36 PM

Page 1

Work Order ID: 165114

165114

Parent Item: D4635-041

D4635-041

Parent Item Name: Fwd Ceiling Panel Assembly, LH

Start Date: 8/2

9/1/2017

Start Qty: 1.0

1.00

Comments:

IPP Rev. A 12/08/09 New Issue DL
12/11/08 Doc Release DL
Update 13/07/09 DL verf:DD
13/12/09 DL
Ipp Rev. E Dwg Update 14/01/09 DL
Dwg. Update 15/01/27 DL

IPP Rev B
IPP Rev. C Dwg.
IPP Rev D Dwg Update
IPP Rev. F

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
---------------------------------	------------------------	---------------	-------------	---------------------	------------------	-----------------	--------------------	----------------	-------------	--------------	---------------	----------------	--------

D4652-5		Manufactured	No			100	Each	11.0000	2	2		SEP 13 2017	
---------	--	--------------	----	--	--	-----	------	---------	---	---	--	-------------	--

D4652-5

Air Valve, 1.25 Id Disk Type

**

Location

Loc Qty

Loc Code

MF003

11

122691

2

155417

9

MS24693-BB51

Purchased

No

100

Each

349.0000

8

8

MS24693-BB51

Screw

**

SEP 13 2017

Location

Loc Qty

Loc Code

ST288

349

m128057

349

D4635-141

Manufactured

No

100

Each

0.0000

1

1

D4635-141

Fwd Ceiling Replacement Panel Assembly, LH

**

SEP 13 2017

Location

Loc Qty

Loc Code

MF009

13

156116

13

D4646-1

Manufactured

No

100

Each

13.0000

2

2

D4646-1

Plenum Cap Assembly

**

SEP 13 2017

2

164198

8

1

DAS
6
9-89

DAS
6
9-89

17/09/15

DAS
6
9-89

Daryl

4

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____		DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐		AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐					
Date :		Step #:		QTY Effective :				MRB (QSI042) Approval	
Description Work Order Deviation				Disposition				Completed By Lead hand / Supervisor Approval Verification QC / QA Coordinator Approval	
Root Cause		FAULT CATEGORY							
Environment ☐	☐ No Re-verification	☐ Pressure/Forced	☐ Temperature/Cure	☐ Power Loss/Surge	☐ Positioned Wrong				
Design ☐	☐ Operator	☐ Bending	☐ Set-up	☐ Folio/Program	☐ Outside Dimensions				
Doc/Data ☐	☐ Offset/Setup	☐ Centre Not Concentric	☐ BOM/Route	☐ Grain	☐ Over/Under tolerance				
Equip/Tooling ☐	☐ Supplier	☐ Cracks	☐ Broken/Damage/Defect	☐ Weld	☐ Part Incorrect				
Handling/Pre ☐	☐ Training	☐ Crimp/Kink/Ripple/Wave	☐ Inspection Incomplete/Unqualified	☐ Wrong Stock Pulled	☐ Part Lost/Missing				
Material ☐	☐ Use for Testing	☐ Cuffs	☐ Contamination	☐ Out of Sequence	☐ Part Moved				
Internal Transport ☐	☐ Poor Information	☐ Crushing	☐ Countersink	☐ Off-set	☐ Drawing				
Tribal Knowledge ☐	☐ Rushing	☐ Heat Treat	☐ Cut Too Short	☐ Mislabeled	☐ Finish				
LOA ☐	☐ Product Improvement	☐ Wave/Twist in Tube	☐ Instructions Incomplete/Unclear	☐ Fit/Function	☐ Misread				
Substation ☐	☐ Process Improvement	☐ Marks/Chatter	☐ Drill Holes	☐ Misaligned/off center	☐ Turning Sequence				
Past Expiry Date ☐	☐ Manufacturing Process	OTHER :							
Misidentified ☐	☐ Past Due								

Picklist Print

Tuesday, August 15, 2017 3:20:36 PM

Page 2

Work Order ID: 165114

165114

Parent Item: D4635-041

D4635-041

Parent Item Name: Fwd Ceiling Panel Assembly, LH

Start Date: 8/21/2017

Required Date: 9/1/2017

Start Qty: 1.00

Required Qty: 1.00

D4655-1

Manufactured No

100

Each

17.0000

2

2

D4655-1

Speaker

**

SEP 13 2017

DAS

6

9-89

Location

Loc Qty

Loc Code

MF002

17

117634

1

154865

16

D4708-9

Manufactured No

100

Each

11.0000

2

2

D4708-9

Lanyard

**

SEP 13 2017

DAS

6

9-89

Location

Loc Qty

Loc Code

MF004

11

154884

11

D4728-041

Manufactured No

100

Each

12.0000

1

1

D4728-041

LH Cabin Speaker #1

**

SEP 13 2017

DAS

6

9-89

Location

Loc Qty

Loc Code

MF002

3

124216

3

MF009

9

124216

9

D4728-043

Manufactured No

100

Each

13.0000

1

1

D4728-043

LH Cabin Speaker #2

**

SEP 13 2017

DAS

6

9-89

Location

Loc Qty

Loc Code

MF002

2

124296

2

MF009

11

124296

11

Tuesday, August 15, 2017 3:20:36 PM

Shop Packet Print

Page 2

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____		DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐		AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐																																																													
Date :		Step #:		QTY Effective :			MRB (QSI042) Approval																																																										
Description Work Order Deviation				Disposition				Completed By Lead hand / Supervisor Approval Verification QC / QA Coordinator Approval																																																									
Root Cause		FAULT CATEGORY																																																															
Environment ☐	No Re-verification ☐	Pressure/Forced ☐	Temperature/Cure ☐	Power Loss/Surge ☐	Positioned Wrong ☐	Design ☐	Operator ☐	Bending ☐	Set-up ☐	Folio/Program ☐	Outside Dimensions ☐	Doc/Data ☐	Offset/Setup ☐	Centre Not Concentric ☐	BOM/Route ☐	Grain ☐	Over/Under tolerance ☐	Equip/Tooling ☐	Supplier ☐	Cracks ☐	Broken/Damage/Defect ☐	Weld ☐	Part Incorrect ☐	Handling/Pre ☐	Training ☐	Crimp/Kink/Ripple/Wave ☐	Inspection Incomplete/Unqualified ☐	Wrong Stock Pulled ☐	Part Lost/Missing ☐	Material ☐	Use for Testing ☐	Cuffs ☐	Contamination ☐	Out of Sequence ☐	Part Moved ☐	Internal Transport ☐	Poor Information ☐	Crushing ☐	Countersink ☐	Off-set ☐	Drawing ☐	Tribal Knowledge ☐	Rushing ☐	Heat Treat ☐	Cut Too Short ☐	Mislabeled ☐	Finish ☐	LOA ☐	Product Improvement ☐	Wave/Twist in Tube ☐	Instructions Incomplete/Unclear ☐	Fit/Function ☐	Misread ☐	Substation ☐	Process Improvement ☐	Marks/Chatter ☐	Drill Holes ☐	Misaligned/off center ☐	Turning Sequence ☐	Past Expiry Date ☐	Manufacturing Process ☐	OTHER :			
Misidentified ☐	Past Due ☐																																																																

Picklist Print

Tuesday, August 15, 2017 3:20:36 PM

Page 3

Work Order ID: 165114

165114

Parent Item: D4635-041

D4635-041

Parent Item Name: Fwd Ceiling Panel Assembly, LH

Start Date: 8/21/2017

Required Date: 9/1/2017

Start Qty: 1.00

Required Qty: 1.00

D4728-059

Manufactured No

100

Each

13.0000

1

1

D4728-059

Cabin Lights Harness

**

SEP 13 2017

DAS
6
8-89

Location

Loc Qty

Loc Code

MF002

3

124187

3

MF009

10

124187

10

D4743-1

Manufactured No

100

Each

20.0000

2

2

D4743-1

Speaker Grill

**

SEP 13 2017

DAS
6
8-89

Location

Loc Qty

Loc Code

MF005

20

154770

4

155856

8

164337

8

MS21044-N08

Purchased No

100

Each

130.0000

8

8

MS21044-N08

Nut

**

SEP 13 2017

DAS
6
8-89

Location

Loc Qty

Loc Code

ST302

130

m131452

12

m136502

18

m136537

100

Nut
D4652-3

M 164538

21

21

OK
17/09/15

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____		DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐		AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐					
Date :		Step #:		QTY Effective :				MRB (QSI042) Approval	
Description Work Order Deviation				Disposition				Completed By	
								Lead hand / Supervisor Approval Verification	
								QC / QA Coordinator Approval	
Root Cause		FAULT CATEGORY							
Environment ☐ Design ☐ Doc/Data ☐ Equip/Tooling ☐ Handling/Pre ☐ Material ☐ Internal Transport ☐ Tribal Knowledge ☐ LOA ☐ Substation ☐ Past Expiry Date ☐ Misidentified ☐	No Re-verification ☐ Operator ☐ Offset/Setup ☐ Supplier ☐ Training ☐ Use for Testing ☐ Poor Information ☐ Rushing ☐ Product Improvement ☐ Process Improvement ☐ Manufacturing Process ☐ Past Due ☐	Pressure/Forced ☐ Bending ☐ Centre Not Concentric ☐ Cracks ☐ Crimp/Kink/Ripple/Wave ☐ Cuffs ☐ Crushing ☐ Heat Treat ☐ Wave/Twist in Tube ☐ Marks/Chatter ☐	Temperature/Cure ☐ Set-up ☐ BOM/Route ☐ Broken/Damage/Defect ☐ Inspection Incomplete/Unqualified ☐ Contamination ☐ Countersink ☐ Cut Too Short ☐ Instructions Incomplete/Unclear ☐ Drill Holes ☐	Power Loss/Surge ☐ Folio/Program ☐ Grain ☐ Weld ☐ Wrong Stock Pulled ☐ Out of Sequence ☐ Off-set ☐ Mislabeled ☐ Fit/Function ☐ Misaligned/off center ☐	Positioned Wrong ☐ Outside Dimensions ☐ Over/Under tolerance ☐ Part Incorrect ☐ Part Lost/Missing ☐ Part Moved ☐ Drawing ☐ Finish ☐ Misread ☐ Turning Sequence ☐				
								OTHER :	

Picklist Print

Tuesday, August 15, 2017 3:20:36 PM

Page 4

Work Order ID: 165114

165114

Parent Item: D4635-041

D4635-041

Parent Item Name: Fwd Ceiling Panel Assembly, LH

Start Date: 8/21/2017

Required Date: 9/1/2017

Start Qty: 1.00

Required Qty: 1.00

MS21919-WDG8

Purchased

No

100

Each

54.0000

6

6

MS21919-WDG8

Clamp

**

SEP 13 2017

DAS
9-89

Location

Loc Qty

Loc Code

over008

49

m137320

25

m138207

24

ST293

5

m136537

5

100

Each

1,962.000

8

8

**

SEP 13 2017

DAS
9-89

NAS1149DN832J

Purchased

No

NAS1149DN832J

Washer

Location

Loc Qty

Loc Code

ST264

1962

M129499

16

M131697

64

M131387

1882

100

Each

2,608.000

7

7

**

SEP 13 2017

DAS
9-89

PLT1.5M-M

Purchased

No

PI T1 5M-M

Tie Wrap

Location

Loc Qty

Loc Code

ST570

2608

m129712

2608

DQA: _____ Date: _____


WORK ORDER NON-CONFORMANCE / UPDATE



QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____		DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐		AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐					
Date :		Step #:		QTY Effective :			MRB (QSI042) Approval		
Description Work Order Deviation				Disposition				Completed By Lead hand / Supervisor Approval Verification QC / QA Coordinator Approval	
Root Cause		FAULT CATEGORY							
Environment ☐	No Re-verification ☐	Pressure/Forced ☐	Temperature/Cure ☐	Power Loss/Surge ☐	Positioned Wrong ☐				
Design ☐	Operator ☐	Bending ☐	Set-up ☐	Folio/Program ☐	Outside Dimensions ☐				
Doc/Data ☐	Offset/Setup ☐	Centre Not Concentric ☐	BOM/Route ☐	Grain ☐	Over/Under tolerance ☐				
Equip/Tooling ☐	Supplier ☐	Cracks ☐	Broken/Damage/Defect ☐	Weld ☐	Part Incorrect ☐				
Handling/Pre ☐	Training ☐	Crimp/Kink/Ripple/Wave ☐	Inspection Incomplete/Unqualified ☐	Wrong Stock Pulled ☐	Part Lost/Missing ☐				
Material ☐	Use for Testing ☐	Cuffs ☐	Contamination ☐	Out of Sequence ☐	Part Moved ☐				
Internal Transport ☐	Poor Information ☐	Crushing ☐	Countersink ☐	Off-set ☐	Drawing ☐				
Tribal Knowledge ☐	Rushing ☐	Heat Treat ☐	Cut Too Short ☐	Mislabeled ☐	Finish ☐				
LOA ☐	Product Improvement ☐	Wave/Twist in Tube ☐	Instructions Incomplete/Unclear ☐	Fit/Function ☐	Misread ☐				
Substation ☐	Process Improvement ☐	Marks/Chatter ☐	Drill Holes ☐	Misaligned/off center ☐	Turning Sequence ☐				
Past Expiry Date ☐	Manufacturing Process ☐								
Misidentified ☐	Past Due ☐	OTHER : _____							



ITEM NO.	QTY. -041	P/N	DESCRIPTION
1	X	D4635-041	LH, FWD CEILING PANEL ASSY
2	1	D4635-141	LH, FWD CEILING REPLACEMENT PANEL ASSY
3	2	D4646-1	PLENUM CAP ASSEMBLY
4	2	D4652-3 (REF)	MOUNTING NUT (PART OF D4652-5)
5	2	D4652-5	AIR VALVE, 1.16 ID DISK TYPE
6	2	D4655-1	SPEAKER
7	2	D4708-9	LANYARD
8	1	D4728-041	LH SPEAKER #1 HARNESS ASSY
9	1	D4728-043	LH SPEAKER #2 HARNESS ASSY
10	1	D4728-059	CABIN LIGHT HARNESS
11	2	D4743-1	SPEAKER GRILL
12	8	MS21044-N08	NUT, SELF-LOCKING
13	6	MS21919WDG8	CLAMP
14	8	MS24693-BB51	SCREW, CSK 100°
15	8	NAS1149DN832J	WASHER
16	7	PLT1.5M-M	TIE-WRAP (OR PLT1.5M-C)

RELEASED

2015 JAN 26

ECN 14-634 4P

F	D4652-5 WAS D4652-1 (ZN D4-1, D4-3, D4-5, D4-7)	RF	14.11.28
E	REVISE BOM (ZN D4-1, D4-3, D4-5, D4-7); ADDED NOTE 11) (ZN A8-9, A8-10, A8-11 & A8-12); REVERSE VIEW -142/-144 (ZN B8-10, B8-12); RANGE 1.5-1.8 WAS 1.8 (ZN A7-17); DIMENSION HAS SHIFTED DUE MATERIAL THICKNESS	RF	14.01.09
D	CORRECTING VIEW FOR ITEM 8 (ZN B2-2); ADDED D5022-1 (ZN D4-9, C3-9, D4-10, C2-10), D5022-3 (ZN D4-11, C5-11), D5022-5 (ZN D4-12, B5-12); DIMENSION SHIFTED DUE ADDING D5022-1/-3/-5; REVISE NOTE 10) (ZN A8-9, A8-10, A8-11, A8-12); NOTE 1) (ZN A8-13, A8-14, A8-14, A8-15, A8-16)	RF	13.12.09
C	REVISE NOTE 8) (ZN A8-9, A8-10, A8-11 & A8-12); 32 WAS 34 (ZN C5-15, B5-16); CORRECT TYPO #1 WAS #3 (ZN D4-3); CHANGE TOLERANCE (ZN C3-13, B2-14, B5-17, B7-17, D2-17, D4-17, A3-18)	RF	13.06.18
B	ADDED D4635-141/-142/-143/-144 (ZN B4-9, B4-10, B4-11, B4-12); REVISE D4635-041/-042/-043/-044 PART LIST & GENERAL NOTES; ADDED D4732-41 (ZN B5-8); CHANGE TO D4743-1 SPEAKER GRILL AND MS24693-BB51 SCREWS (SHT 1, 3, 5, 7); ADD VIEWS R'-R' (ZN A7-17) AND S'-S' (ZN A5-17); UPDATE DETAIL 'D' (ZN C7-18)	RF	12.11.30
A	NEW ISSUE	RF	12.07.25
REV.	DESCRIPTION	BY	DATE
DESIGN	RF	DART AEROSPACE LTD HAWKESBURY, ONTARIO, CANADA	
DRAWN	RF		
CHECKED	AK	DRAWING NO.	REV. F
MFG. APPR.	DL	D4635	SHEET 1 OF 18
APPROVED	HS	TITLE	SCALE
DE APPR.	DS	OUTBOARD CEILING PANELS	NTS
DATE	14.11.28	COPYRIGHT © 2012 BY DART AEROSPACE LTD THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.	

APPROVED

